

# NOTICE TO MARINERS

## №6 – 2024

### HEYSHAM HARBOUR

#### LINKSPAN №1 – SPEED WITHIN THE HARBOUR

NOTICE IS HEREBY GIVEN that over this morning's low water period, one of the shoreside securing points on Linkspan №1 (which is out of use) failed.

While remedial work takes place, all vessels must navigate within the Harbour at minimum safe speed to reduce the effects of wash and interaction on Linkspan №1.

Heysham Port Control will also issue local navigation warnings supporting this Notice.