


## **NOTICE TO MARINERS**

## No. 54 - 2024

## River Medway – Saltpan Reach Discontinuation of Mooring Buoys

**Notice is hereby given that** Saltpan No.1 and No.2 mooring buoys have been discontinued, the riser chains for both buoys have been lowered to the seabed and will not be recovered. The UKHO have been informed of the change which will be reflected in future Admiralty Notice to Mariners. Until the respective admiralty charts have been updated to denote the foul area, mariners are advised not to anchor in the vicinity of the mooring buoys currently shown below.



Admiralty Chart Nos.3683 and 1834 refer.

Further information may be obtained from Medway VTS on VHF Channel 74, call sign "Medway VTS" or telephone 0151 949 6148 or 0151 949 6650. (Recorded Lines)

Marine Operations Department Peel Ports London Medway

27th September 2024